

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1		219	E	44.29867. -69.00018							
19			E	44.29845 -m 69.00078							Several Measurable Ash behind Pole #219
20											
21			W	44.29858 - 69.00098	D	Ash	Inv	32	16	In Decline	RPZ extends 2 feet under pavement
22			W	44.29858 - 69.00098	D	Maple	Inv	18	9	Good	RPZ is 9 feet in ROW. Drainage ditch is in RPZ
23			W	44.29856 - 69.00113	D	Red Oak	Inv	31	15.5	In Decline	RPZ extends under pavement. Drainage ditch is in RPZ
24		218	E	44.29844. -69.00158							
25			W	44.29852 - 69.00147	D	Red Oak	Inv	23	12.5	In Decline	Drainage ditch in RPZ
26			E	44.29837 - 69.00156		Oak					2779 Atlantic Highway. Arborvitae Hedge on both sides of driveway. RPZ borders ROW
27			E	44.29830 - 69.00209	?	?	Group	12	6	Fair	Beyond the ROW. Drainage ditch is in RPZ. 2274 Atlantic Highway
28		217 Double Pole	E	44.29853. -69.00132							
29			E	Hedge Removed	NA	NA	NA	NA	NA	NA	(Rosa Ragosa?) hedge 10 feet beyond ROW
30			W	44.29845 - 69.00216							Small maples. Cedar shrub located on driveway" island"
31		216	E	44.29834. -68.00236							
32			W	44.29841 - 69.00250	E	Wolf Pine	Inv	16	8	Good	Located 7 feet in ROW. Drainage ditch in RPZ
33			E	44.29823 - 69.00284							2767 Atlantic Highway. Fence is 8 feet from Pavement and 6 feet in ROW. Arborvitae hedge behind fence. Tom Osgood's
34		215	W	44.29837. -69.00310							At South Cobbtown
35			E	44.29825 - 69.00336							Lilac hedge 3 feet in ROW at Cobbtown Road

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1			W	44.29646 -69.00734	E	Shrubbery	Group				Landscaping shrubbery. 2702 Atlantic Hwy
53											
54		205	W	44.29534 -69.00777							
55		204	W	44.29516 -69.00765							At Ducktrap Road
56			W	44.29509 -69.00761	D	Apple	Inv	14	7	Good	At Ducktrap road
57		203	W	44.29450 -69.00789							
58		202, 201,200	W	44.29387 -69.00784							Triple Poles with Transformers
59		199.5	W	44.29356 -69.00778							
60			W	44.29331 - 69.00794							Interesting Shrub - Notable. Photo for ID - Similar to a Bay or Mangrove
61			E	44.29332 -69.00778	D/E	Red Maple/Spruce	Group	10	5	Good	2669 Atlantic Hwy. Line of Landscaping Shrubbery outside ROW. Large Wolf Pine outside ROW
62		199	W	44.29339 -69.00785							
63			W	44.29312 -69.00791	E	White Spruce	Inv	33	16.5	Good	Sideswiped by CMP. Opposite Mike's Alignment
64			W	44.29271 -69.00797	D	Red Oak	Group	22	11	Good	Cluster of 5. 2664 Atlantic Hwy. Landscape Shrubbery; Apple, Spruce, more
65		198	W	44.29258 -69.00791							
66			W	44.29203 - 69.00798							CMP Poles 198 - 196 old sidewalk. Scrub growth within ROW. Culvert at old sidewalk
67			E	44.29148 -69.00790	E	Spruce	Inv	20	10	Good	Just overlapping ROW
68		196	W	44.29137 -69.00816							Just north of Bayside Church
69			E	44.29113 -69.00780	D	Maple	Inv	21	10.5	Good	Sugar Maple RPZ= Dripline

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1			E	44.29116 -69.00782	D	Ornamental Snowball	Group	16	8	Good	3 Ornamental Dooryard Snowball Bushes
70			W	44.29098 -69.00809	D	Landscaping Lilac	Inv	24	12	Good	Beneath powerlines in church dooryard in ROW
71											
72		195	W	44.29087 -69.00794							
73			W	44.29080 -69.00809	D	Poplar	Inv	40	20	Good	Androscoggin Poplar Outside of ROW
74			W	44.29087 -69.00797	D	3 Maples	Group	24	12	Good	2630 Atlantic Hwy. 4 ft. RPZ overlap into ROW. 4th maple RPZ outside ROW
75			W	44.29044 -69.00822	D	Red Oak	Inv	16	8	Good	2630 Atlantic Hwy.
76			E	44.29061 -69.00790	D	Red Oak	Inv	22	11	Good	Within ROW (Overlap 17 ft ROW>RPZ)
77			E	44.29049 -69.00803	D	Red Oak	Inv	26	13	Good	Inside ROW. (Overlap 18 ft ROW>RPZ). 7 measurable Ash to Brace Pole 194 S.
78		194	W	44.29035 -69.00808							
79			E	44.29022 -69.00799	D	Slippery Elm	Inv	22	11	Good	next to 21 inch DBH Birch
80			E	44.29017 -69.00806	D	Ash	Inv	13	6.5	Good	16 ft. RPZ>ROW overlap. 1 Elm, 6 Ash to south pole
81			E	44.29003 -69.00805	D	Red Oak	Inv	14	7	Good	17 ft. RPZ>ROW overlap at Patterson Road
82			W	44.290003 -69.00833	D	Red Oak	Inv	17	8.5	Good	2030 Atlantic Hwy. 4 ft. RPZ>ROW overlap
83		193	W	44.28969 -69.00833							Between 193 - 192 open dooryard (2618 Atlantic Hwy.)
84			E	44.28971 -69.00818	D	Red Oak	Inv	14	7	Good	12 ft. RPZ>ROW overlap. 10 inch spruce to the north. Several smaller Ash to the south
85			E	44.28954 -69.00815	D	Slippery Elm	Inv	16	8	Good	19 ft. RPZ>ROW overlap. 10 inch Ash and several smaller Ash and Spruce north
86		192	W	44.28954 -69.00844							

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1			E	44.28940 -69.00814	D	Ash	Group (2)	14	7	Good	16 ft. RPZ>ROW overlap
87			E	44.28929 -69.00822	E	White Pines	Group	14	7	Good	Some 6 inch Oak North of driveway. Several 10 inch Ash to the south. 18 ft. RPZ>ROW overlap
88			E	44.28889 -69.00833	E	Hemlock	Group (4)	20	10	Good	2607 Atlantic Hwy. 15 ft. RPZ>ROW overlap
89			E	44.28874 -69.00842	D	Red Oak	Group	14	7	Good	10 ft. RPZ>ROW overlap. White Birch and Hemlocks to south
90			E	44.28874 -69.00842	D	Red Oak	Group	14	7	Good	10 ft. RPZ>ROW overlap. White Birch and Hemlocks to south
91		191.5(?)	W	44.28894 -69.00835							Missed Numbered Pole. (Old #502.5)
92			W	44.28868 -69.00841	D	Red oak	Inv	16	8		Good 6 ft. RPZ>ROW overlap
93			W	44.28871 -69.00847	E	White Pines	Inv	22	11	Good	M DOT Supply Yard
94			E	44.28865 -69.00831	E	Spruce	Inv	18	9	Good	16 ft. RPZ>ROW overlap. 12 inch Cedar in ROW to the south
95			E	44.28855 -69.00835	D	Red Oak	Group (3)	16	8	Good	8 ft. RPZ>ROW overlap
96			E	44.28847 -69.00840	D	Ash	Inv	36	18	Good	Monster Ash with ???. 21 ft RPZ>ROW overlap. Cluster Red maple and Red Oak north. 2597 Atlantic Hwy.
97		191	W	44.28813 -69.00836							
98			W	44.28877 -69.00808	E	White Pine	Inv	16	8	Good	3 ft. withn ROW. Just north of Carver Lane. 11 ft. RPZ>ROW overlap Invasive M.F.R. 8'x16'
99			E	44.28882 -69.00825	D	Chinese Maple	Inv				To CMP Pole #190 Carver Lane. (3") #2597 Atlantic Highway
100			W	44.28820 -69.00825	E	White Pine	Inv	16	8	Scrubby	2 ft RPZ>ROW
101		190	W	44.28812 -69.00851							
102			E	44.28828 -69.00825	D	Red Oak	Inv	9	4.5	Good. Road Lean	4 ft RPZ>ROW
103			E	44.29790 -69.00855	D	Red Maple White Ash	Group	29	14.5	Old/In Decline. Old/In Decline	2 ft RPZ>ROW

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1			E	44.28805 -69.00854	D	Red Maple	Inv	16	8	Good	Double Trunk. 4 ft. RPZ>ROW
104			E	44.28794 -69.00843	E	White Pine	Inv	32	16	Good	14 ft. RPZ>ROW. (1st)
105			E	44.28803 -69.00839	D	Red Maple	Inv	12	6	Good	4 ft RPZ>ROW
106			E	44.28794 -69.00843	E	White Pine	Inv	32	16	Good	14 ft RPZ>ROW (2nd)
107			E	44.28794 -69.00843	E	White Pine	Inv	32	16	Good	14 ft RPZ>ROW (2nd)
108		189	W	44.28748 -69.00859							
109			E	44.28777 -69.00849	D	Red Oak	Group	10/9	5	Double. Good/Bad	7 ft. RPZ>ROW. CMP Service entrance clipped top of bad oak and it leans toward road
110			E	44.28771 -69.00850	E	White Pine	Inv	30	15	Good but in decline	12 ft RPZ>ROW
111			E	44.28769 -69.00850	D	Red Oak	Inv	11	5.5	Good.	No Overlap. No top. Leans to road. Drainage ditch 4 ft to the south
112			E	44.28758 -69.00851	D	White Ash	Inv	12	6	Good	2 fr. RPZ>ROW. At corner of #2587 Atlantic Highway
113			E	44.28751 -69.00859	E	Spruce	Inv	10	5	Good	RPZ is ROW. White Pine, Red Pine on embankment. Well is located behind the Spruce
114			W	44.28774 -69.00860	D	Silver <Maple	Inv	24	12	Great	No RPZ/ROW overlap
115			W	44.28766 -69.00860	E	Arborvitae	Group				1.5 ft RPZ>ROW. Group of 20.
116			W	44.28746 -69.00870	E	Spruce	Inv	14	7	Good	No RPZ/ROW Overlap
117			W	44.28757 -69.00886	D	Popple	Group	18	9	In Decline	1.5 ft. RPZ>ROW. Group of 4
118		188	W	44.29734 -69.00845							
119			W	44.28740 -69.00872	D	Sugar Maple	Inv	46	23	Good	16 ft RPZ>ROW. Located just south of CMP Pole #188. #2596 Atlantic Highway. Windsor Chair
120			W	44.28722 -69.00875	D	Crab Apple	Inv	9	4.5	Good	

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1			E	44.28521 -69.00865	E	Spruce	Inv	7	3.5	Good	3 ft. RPZ>ROW.
155			E	44.28507 -69.865	D	Sugar Maple	Inv	30	15	In Decline*	13 ft. RPZ>ROW. *From being trimmed Hard
156			E	44.28493 -69.00860	D	Horse Chestnut	Inv	8	4	Good	2 ft. RPZ>ROW.
157			E	44.28493 -69.00860	D	Horse Chestnut	Inv	8	4	Good	2 ft. RPZ>ROW.
158		183	W	44.28515 -69.00865							
159			W	44.28520 -69.00888	E	Spruce	Inv	8	4	Good	4 ft. RPZ>ROW. Adjacent to culvert
160		183.1	E	na							
161			E	44.28528 - 69.00855	E	Spruce	Inv	8	4	Good	4 ft RPZ > ROW
162			E	44.28510 - 69.00860	D	Sugar Maple	Inv	31	16	Good	4ft. RPZ > ROW
163			E	44.28507 - 69.00861	D	Sugar Maple	Inv	31	16	In Decline	8 ft. RPZ > ROW
164			E	44.28495 - 69.000865	D	Horse Chestnut	Inv	8	4	Good	9 ft RPZ > ROW
165			E	44.28488 - 69.00850	D	Sugar Maple	Inv	29	15	In Decline	9 ft. RPZ > ROW
166			E	44.28475 - 69.00853	D	Flowering Quince	Inv	X	X	X	For Refernce Only
167		182	W	44.28473 - 69.00878							at Lily Lane
168			E	44.28464 - 69.00847	D	Sugar Maple	Inv	28	14	In Decline	9 ft.RPZ >ROW
169			E	44.28463 - 69.00859	D	Maple	Inv	15	8	In Decline	13 ft RPZ > ROW
170			W	44.28439 - 69.00859	D	Maple Ash	Inv	16	8	In Decline	3 ft. RPZ> ROW. Maple Ash?
171		181	W	44.28430. -69.00860							

	A	B	C	D	E	F	G	H	I	J	K
1	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
189		172	W	44.28014. -69.00902							
190			E	44.28012 - 69.00899	D	Maple	Group	23	12	Good	11 ft. RPZ > ROW. ROW extends 8 feet beyond tree
191			E	44.28003 - 69.00895	D	Sugar Maple	Inv	20	10	Good	ROW extends 12 feet beyond (east) of tree. At 2477 Atlantic Hwy
192			E	44.27998 - 69.00891	D	Ash	Group	20	10	In Decline	ROW extnds 10 feet beyond (east) of tree. Three leader Ash
193			E	44.27986 - 69.00893	D	Maple	Inv	16	8	Good	ROW extends 11 feet beyond (east) of tree.
194			E	44.27979 - 69.00906	D	Ash Clutch	Group	22	11	Good	ROW extend 3 feet beyond (east) of tree
195		171	W	44.27977. -69.00914							2478 Atlantic Hwy.
196			E	44.2796 - 69.00905	D	Red Oak	Inv	30	15	Good	20 ft. RPZ> ROW. 1 Stump Pair
197			E	44.27971 - 69.00899	D	Red Oak	Inv	10	5	Good	3 ft RPZ > ROW. 1 Clutch (4 stems)
198			E	44.27962 - 69.00904	D	Red Oak	Inv	12	6	Good	3 ft. RPZ > ROW
199			E	44.27955 > 69.00907	D	Red Oak	Inv	58	29	Good	Entire Tree in ROW. 1 main leader Broken. 1 Branch Now Trying to Self Correct
200			E	44.27945 - 69.00916	D	Red Maple	Inv	30	15	Good	18 ft. RPZ > ROW. Lilac in fron of house. 2469 Atlantic Hwy.
201			E	44.27941 - 69.00922	D	Black Locust	Inv	58	29	Good	34 ft. RPZ > ROW. 2 Leaders. (Almost to center of highway)
202			E	44.27933 - 69.00932	D	Crab Apple	Inv	12	6	Good	15 ft. RPZ > ROW
203			W	44.27976 - 69.00925	E	Arborvitae	Inv	48	24	Good	19 ft. RPZ > ROW. Many leaders
204		170	E	44.27936. -69.00943							French Cemetary
205			E	44.27923 - 69.00937	D	Red Oak	Inv	8	4	In Decline	4 ft. RPZ > ROW. 5 Leaders. (Culvert 15 ft. southwest - 5 small Ash by culvert)

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1											
206		169	W	44.27899. -69.00969							
207			W	44.27898 - 69.00980	D	Maple	Inv	20	10	Good	RPZ Borders Ditch
208			W	44.27888 - 69.00988	D	Chinese Maple	Inv	18	9	Good	9 ft. RPZ > ROW. 2460 Atlantic Hwy
209			W	44.27857 - 69.00997	E	Cedar Hedge				Good	11 ft. from Pavement. Borders Ditch. 2456 Atlntic Highway
210		168.1	E	44.27873. -69.00973							Dot's
211			E		D	Lilac/Arborvitae					Just on Boarder - Group of various Landscape Shrubs in fron of 2453 Atlantic Hwy
212		168	W	44.27850. -69.01001							Green Tree Coffee Roasters
213			E	44.27814 - 69.01011	E	Red Pine	Group	12	6	In Decline	9 ft. RPZ > ROW. Group of 3 trees. Well casing between two trees
214			E	44,27810 - 69.01004	E	Arborvitae	Group			In Decline	9 ft. RPZ > Row. A few Red Pine just out of ROW. 2447 Atlantic Hwy.
215		167	W	44.27802. -69.01035							
216			E	44.27789 - 69.01019	D	Ash	Inv	10	5	Good	10 ft. RPZ > ROW. Bitterset Observed. Couple of small ash to the south. 4 ft in ROW
217		166.1	E	44.27751. -69.01054							Shag Rock
218		166	W	44.27754. -69.01064							Native shrubs on south side, east nd west to next span
219			E	44.27717 - 69.01067	D	Sugar Maple	Inv	15	7.5	Good	7 ft. RPZ > Row. 2 leaders. 2344 Atlantic Hwy.
220			E	44.27714 - 69.01074	E	Red Pine	Inv	14	7	In Decline	9 ft. RPZ > ROW
221		165	W	44.27692. -69.01091							
222		165.1	E	44.27691. -69.01088							

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1											
223		164	W	44.27667 -69.01124							Reeds Ln
224		164.1	E								
225			E	44.27647 - 69.01112	D	Ash	Inv	41	20.5	Good	17 ft. RPZ > ROW. 6 ft. in ROS. 2419 Atlantic Hwy
226			E	44.27641 - 69.01121	D	Maple	Inv	38	19	In Decline	23 ft. RPZ > ROW. Missing one of three leaders. With cable. 2419 Atlantic Hwy
227			E	44.27635 - 69.01120	E	Arborvitae	Inv	32	16	Not Bad	21 RPZ > ROW. Three of six leaders broken. 2419 Atlantic Hwy
228			E	44.27623 - 69.01131	D	Ash	Inv	58	29	Starting Decline	33 ft. RPZ > ROW. 2419 Atlantic Hwy.
229		163	W	44.27638 -69.01144							
230			E	44.27620 - 69.01134	E	Spruce	Inv	12	6	Good	7 ft. RPZ > ROW. East of Lawrence Road
231			E	44.27620 - 69.01134	D	Ash	Inv	8	4	Good	5.5 ft. RPZ > ROW
232		162.1	E	44.27589 - 69.01163							Stub Service. Inside Fence
233			E	44.27590 - 69.01163	D	Ash	Inv	34	17	Good	16.5 RPZ > ROW. @ main leaders, 16 inches each
234		162	W	44.27594 - 69.01170							
235			E	44.27568 - 69.01172	D	Beach	Inv	14	7	Goo	No overlap. Inside Fence. No Beach Wilt yet but close by
236			E	44.27561 - 69.01173	D	Beach	Inv	48	24	Good. Some wilt	7 ft. RPZ > ROW. Four main leaders at ground level. One leader in ROW
237			E	44.27554 - 69.01181	E	Spruce	Inv	13	6.5	Good	No overlap. 2407 - 2411 Atlantic Hwy, end of fence
238			W	44.27586 - 69.01167	E	White Pine	Inv	12	6	Good	Trace of RPZ overlap in ROW. 2412 Atlantic Hwy
239			W	44.27562 - 69.01184	E	White Pine	Inv	16	8	Good	Trace of RPZ overlap in ROW. 2412 Atlantic Hwy at Old Stone Road

	A	B	C	D	E	F	G	H	I	J	K
1	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
240		161	W	44.27552 - 69.01204							
241			E	44.27542 - 69.01200	D	Ash	Inv	16	8	Good	8 ft. RPZ > ROW
242			E	44.27515 - 69.01197	D	Ash	Inv	32	16	Good	16 ft. RPZ > ROW
243			E	44.27515 - 69.01206	D	Ash	Inv	45	22.5	Good	22 ft. RPZ > ROW. Lincolnville Health Center
244		160	W	44.27515 - 69.01226							
245			E	44.27502 - 69.01214	D	Red Maple	Inv	45	22.5	Good	No overlap
246			W	44.27494 - 69.01239	E	Arborvitae	Group	18	9	Good	8 ft. RPZ > ROW. Old hedge
247		159	W	44.27481 - 69.01250							
248		158	W	44.27442 - 69.01272							
249		157	W	44.27399 - 69.01301							
250			E	44.27396 - 69.01293	D	Copper Beach	Inv	54	27	In Decline	23 ft. RPZ > ROW. 2381 Atlantic Hwy. Don's house
251			E	44.27365 - 69.01302	D	Black Walnut?	Inv	16	8	Good	No overlap. 2381 Atlantic Hwy. Don's house
252			E	44.27361 - 69.01307	D	Black Walnut?	Inv	30	15	Good	12 ft. RPZ > ROW. 2381 Atlantic Hwy. Don's house
253		156	W	44.27362. -69.01323							
254			E	44.27342 - 69.01319	D	Ash	Clutch	24	12	Good	6 ft. RPZ > ROW. 2381 Atlantic Hwy. Don's house
255			E	44.27352 - 69.01329	D	Cherry	Inv	16	8	Good	4 ft. RPZ > ROW
256		155	W	44.27323 - 69.01348							

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1		Unmarked CMP	W	44.27298 - 69.01376							At Viking Lumber
257		Unmarked CMP	W	44.27239 - 69.01404							At Viking Lumber
258		Unmarked CMP	W	44.27239 - 69.01404							At Viking Lumber
259		Unmarked Stub	E	44.27285 - 69.01354							Power Service for Harbour Pointe
260			E	44.27272 - 69.01364	D	Ash	Group (4)	12	6	Good	RPZ is 6 Feet outside the ROW No ROW/RPZ Overlap
261			E	44.27633 - 69.01315	D	Ash	Group	12	6	Good	RPZ is 1 foot outside the ROW. Cluster of 2
262			E	44.27252 - 69.01388	D	Black Locus	Group	6	3	Good	3 ft. RPZ > ROW. Several Black Locus
263		153?	W	44.27.27210 - 69.0432							
264			E	44.27227 - 69.01400	D	Ash	Inv	18	9	Good	7 ft. RPZ > ROW
265		152	W	44.27178. -69.01458							
266			E	44.27204 - 69.01423	D	Apple	Group	10	5	Good	RPZ is 6 Feet outside the ROW
267			E	44.27160 - 69.01464	D	Ash	Group	10	5	Good	RPZ is 6 Feet outside the ROW
268		151	W	44.27149. - 69.01484							
269		150	W	44.27119. - 69.01514							
270			E	Unmarked Stub Pole							
271			E	44.27071 - 69.01542	D	Ash	Inv	34	17	Good	4 ft. RPZ > ROW. (RPZ is 100% of ROW)
272		149	W	44.27068. - 69.01541							Tagged as #456?
273			E	44.27052 - 69.01540	D	Ash	Inv	36	18	In Decline	2 ft. RPZ > ROW. (RPZ is 100% of ROW)E

	A	B	C	D	E	F	G	H	I	J	K
1	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
274			E	44.27020 - 69.01553	D	Ash	Group	8	4	Good	2 ft. RPZ > ROW. Cluster of 3
275		148	W	44.27019. - 69.01570							
276		148S	E	44.27008. - 69.01554							
277			E	44.27006 - 69.01569	D	Ash	Inv	16	8	Good	9 ft. RPZ > ROW
278			E	44.20995 - 69.01578	D	Ash	Inv	10	5	Good	5 ft. RPZ > ROW. Bill Monroe Driveway. Cluster Qsh/Birch/Spruce. Arborvitae 40 feet long
279		147	W	44.26975. - 69.01603							
280			W	44.26977 - 69.01595	E	Spruce	Inv	14	7	Good	2 ft. RPZ > ROW. Adjacent Culvert
281			E	44.26962 - 69.01606	D	Ash	Inv	16	8	Good	8 ft. RPZ > ROW. Cluster of White birch and Arborvitae Back To Monrow Driveway
282			E	44.26909 - 69.01631	E	White Pine	Inv	23	11.5	Good	11.5 ft. RPZ > ROW
283			W	44.26912 - 69.01648	D	Red Oak	Inv	36	18	Good	RPZ in ROW
284		146	W	44.26905. - 69.01635							
285			E	44.26892 - 69.01662	E	Arborvitae	Group	10	5	Good	No RPZ/ROW Overlap. Cluster of Arborvitae and Ash.
286			E	44.26892 - 69.01662	D	Ash	Group	8	4	Good	No RPZ/ROW Overlap. Group of 3. Adjacent of Saltwater Farm Driveway
287		145	W	44.26866. - 69.01661							
288		144	W	44.26829. - 69.01678							
289		143	W	44.26787. - 69.01696							
290			E	44.26753 - 69.01726	D	Ash	Group	34	17	Fair	7 ft. RPZ > ROW. Cluster of 4 large Ash. Big Old Oak out of ROW. 2284 Atlantic Highway

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1			E	44.26776 - 698.01701	D	White Ash	INV	19	9	Fair	2 ft out of ROW. No Overlap
291			E	44.26747 - 69.01720	D	White Ash	INV	33	16.5	Good	8 ft. RPZ > ROW
292			E	44.26747 - 69.01722	D	White Ash	INV	16	8	Good	2 ft. RPZ > ROW
293			E	44.26739. -69.01747							
294	142		W	44.26739. -69.01747							
295			E	44.26738 - 69.01730	D	White Ash	INV	24	12	Fair	5 ft. RPZ > ROW. Split Tree. Two 24 " Total Trunk 48". 14" Red Oak Five ft. behind.
296			E	44.26719 - 69.01747	D	White Ash	INV	16	8	Fair	Split Trunk. No RPZ/ROW Overlap
297			E	44.26717 - 69.01751	E	Spruce	INV	16	8	Good	No RPZ/ROW Overlap. 2275 Atlantic Highway
298			E	44.26702 - 69.01750	D	White Ash	INV	9	4.5	Good	No RPZ/ROW Overlap. (Large Cedar Out). (RSD Maple Out)
299			E	44.26685 - 69.01776	D	Cherry	INV	24	12	Fair	RPZ = ROW. (Two large Ash Out). Stone
300			W	44.26721 - 69.01760	D	White Ash	INV	22	11	Good	3 ft. RPZ > ROW. (Line of Cedar 18" outside of ROW). 2276 Atlantic Highway
301	141		W	44.26739. - 69.01747							
302			W	44.26061 - 69.01791	E	Spruce	INV	10	5	Good	No RPZ/ROW Overlap. (A coupe of Arborvitae)
303			E	44.26673 - 69.01773	D	White Ash	INV	18	9	Good	RPZ 7 ft. out of ROW. (Two adjacent White Ash of imilar size out of ROW)
304			E	44.26659 - 69.01779	D	White ASH	INV	24	12	Good	RPZ 2 ft. out of ROW.
305			E	44.26660 - 69.01780	D	Red Maple	INV	24	12	Good	RPZ 2 ft. out of ROW.
306	140		W	44.26652. -69.01802							
307			E		D	White Ash	INV	24	12	Poor	RPZ 2 ft. out of ROW. One of three Ash by Pole #139 CMP Service

	A	B	C	D	E	F	G	H	I	J	K
1	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
308			E	44.26603 - 69.01814	D	White Ash	INV	16	8	Good	RPZ 8 ft. out of ROW.
309			E	44.26591 - 69.01828	D	White Ash	INV	24	12	Good	RPZ 8.5 ft. out of ROW. (Four adjacent Ash and one Arborvitae)
310		139	W	44.26610. - 69.01844							Black Horse Inn
311		139.01	E	44.26593 - 69.01841							Service to Residence
312			E	44.26568 - 60.01831	E	Arbortvitae	Group	10	5	Good	RPZ 8.5 ft. out of ROW. (One large Ash and two Arborvitae adjacent.). 18" drainage pipe adjacent
313			W	44.265674 - 69.01879	D	Red maple	INV	14	7	Good	RPZ 6 ft. out of ROW. (String of Maple and Ash at Black Horse Inn out of ROW)
314		138	W	44.26569 - 69.01862							Black Horse Inn
315		137	W	44.26534 - 69.01886							
316			E	44.26526 - 69.01896							String of Young Locus Grove, 2235 Atlantic Highway
317		136	W	44.26491 - 69.01902	D	Ash	INV	14	7	Good	RPZ is 6 ft Out of ROW. String of Young Locus Grove, also Ash and Maple.
318		135 1/2	W	44.26471 - 69.01921							
319			E	44.26453 - 69.01902	E	Spruce	INV	8	4	Good	RPZ is 2 ft Out of ROW.
320		135 1/2	E	44.26453 - 69.01919							
321			W	44.26452 - 69.01899	D	Ash	Group	14	7	Good	RPZ is 6 ft Out of ROW. Group of two Ash. (Bott Lane. Pair of Locus 14" and 10" out of ROW)
322		135	W	44.26442 - 69.01918							
323			E	44.26447 - 69.01903	D	Locus	Group	14	7	Good	RPZ Out of ROW. Group of two
324			E	44.26447 - 69.01903	D	Locus	Group	10	5	Good	RPZ Out of ROW. Group of two

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1			E	44.26428 - 69.01916	D	Locus	INV	28	14	Goup	9 ft. RPZ > ROW. Two leaders. Driveway for Lincolville Motel.
325			E	44.26413 - 69.01907	E	Arborvitae	Group	6	3	Good	2 ft. RPZ > ROW. String of 25 Arborvitae
326											
327		134	W	44.26394. -6901933							
328			W	44.26379 - 69.01941	E	Arborvitae	Group	8	4	Good	Arbovitae Group. No overlap
329			W	44.26371 - 69.01942	D	Ash	Inv	18	9	Good	1 ft. RPZ > ROW; site of shore school historical marker
330			E	44.26392 - 69.01916	D	Ash	Group	45	22.5	Good	Twin trees. No overlap
331			E	44.26305 - 69.01924	D	Ash	Inv	30	15	Good	5 ft RPZ > ROW
332		133	W	44.26354 - 69.01938							
333			E	44.26341 - 6901939	D	Ash	Group	6	3	Good	3 ft. RPZ > ROW. Stub Pole 133.5. Grove of 36 from Lincolville Motel to Bay Road
334			W	44.26333 - 69.01960	D	Sugar Maple	Inv	24	12	Fair	No overlap
335			W	44.26326 - 60.01965	D	Sugar Maple	Inv	16	8	Decline	No overlap
336		132	W	44.26317. -69.01968							
337			E	44.26304 - 69.01961	E	Arborvitae	Group	6	3	Good	3 ft. RPZ > ROW
338		131	W	44.26285. -69.01984							
339		130	W	44.26249. -69.02021							At Wondeer Place
340		129	W	44.26210. -69.02053							
341			E	44.26781 - 69.0234	D	Red Oak	Inv	10	5	Good	3 ft. RPZ > ROW

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1											
342			W	44.26185 - 69.02065	E	Spruce	Inv	7	3.5	Good	3 ft. RPZ > ROW. 10" Maple, 13" Ash closeby under powerline. Stonewall
343		128	E	44.26174 - 69.02081							
344			E	44.26162 - 69.02065	E	White Pine	Inv	28	14	Fair	8 ft. RPZ > ROW. Our Road; 2183 Atlantic Hwy
345			E	44.26152 - 69.02068	E	White Pine	Inv	20	10	Decline	4 ft RPZ > ROW
346			E	44.26150 - 69.02084	E	White Pine	Inv	24	12	Good	6 ft. RPZ > ROW. Stonewall
347		127.5	W	44.2614 - 69.02102							
348			E	44.26135 - 69.02090	E	Arborvitae	Group	11	5.5	Good	3 ft. RP> ROW. Stonewall
349		127	W	44.26120 - 69.02127							At Iron Bluff Road
350			W	44.26097 - 69.02152	E	Fir	Inv	14	7	Fair	2 ft. RPZ > ROW. At Waldo County Soil Distric SignSeveral Spruce; Oak in similar proximity
351		126	W	44.26089. -69.02156							
352			E	44.26046 - 69.02177	D	Red Oak	Group	14	7	Good but Vined	7 ft. RPZ >ROW. Two additional Red Oaks
353			W	44.26075 - 69.02171	D	Maple	Inv	20	10	Good	No overlap. Outside by 3 ft. Culvert adjacent
354		125	W	44.26053 - 69.02190							
355			E	44.26031 - 69.02185	D	Red Oak	Group	32	16	Good	6 ft. RPZ>ROW
356			E	44.26029 - 69.02227	D	Red Oak	Group	28	14	Good	1.5 ft. RPZ >ROW. Two pair of Red Oaks. Shrubs and drainage issue
357			E	44.26002 - 69.02201							Stub Pole 124.1. Stonewall (landscaped) 3 ft. in ROW
358		124		44.26016 - 69.02253							Mt. Battie Motel

	A	B	C	D	E	F	G	H	I	J	K
	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
1			E	44.25976 - 69.02262	D	White Birch	Group	12	6	Good	3 ft. RPZ > ROW
359			E	44.25965 - 69.02262	D	Red Oak	Group	28	14	Good	3 ft. RPZ > ROW
360											
361		123	W								Mt. Battie Motel
362			E	44.25929 - 69.02296							Fence 2 feet in ROW. Row of 16 arborvitae. Note: Fence is west side of route 1 at Mt. Battie Motel
363			E	44.25914 - 69.02297	D	Red Oak	Group	42	21	Good	16 ft. RPZ > ROW. 2.5 ft underpavement
364			E	44.25902 - 69.02311	D	Red oak	Inv	32	16	Good	14 ft. RPZ > ROW. 1 ft under pavement
365		122	W	44.25909 - 69.02327							At Fullington Road
366			E	44.25911 - 69.02313	D	Red Oak	Inv	34	17	Good	11 ft. RPZ>ROW. At Glmore sign
367			W	44.25910 - 69.02345	D	Red Oak	Inv.	28	14	Good	1 ft. RPZ > ROW
368			W	44.25888 - 69.02371	E	Hemlock	Group	20	10	Good	2 ft. out of ROW. Two clutches of Hemlock
369			E	44.25868 - 69.02363	D	Ash	Group	22	11	Good	Stonewall at driveway
370		120	W	44.25860 - 69.023393							NOTE: No CMP #121
371		120.1	E								Stub
372		119	W	44.25821 - 69.02439							At Family Dentistry
373			E	44.25805 - 69.02438	D	Maple	Group	12	6	Good	1 ft. RPZ > ROW. Clutch of 3. Old culvert 30 feet east
374			E	44.25792 - 69.02458							Group of a dozen mixed Birch/Ash/Oak in span. Long stretch. GPS at cluster of Birch
375			E	44.25790 - 69.02463	D	White Birch	Inv.	14	7	Good	2 ft. out of ROW. 2121 Atlantic Hwy.

	A	B	C	D	E	F	G	H	I	J	K
1	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
376		118	W	44.25781 - 69.02489							
377			E	44.25749 - 69.02527	E	Spruce	Inv.	16	8	Good	RPZ = ROW. Fire Road #6. Adjacent culvert
378			E	44.25751 - 69.02541	D	Red Maple	Group	6	3	Good	1 ft. out of ROW. Clutch of several
379		117	W	44.25744. -69.02545							
380			E	44.25727 - 69.02552	D	Red Maple	Inv	9	4.5	Good	RPZ = ROW. Fire Road #5. Nyoka Lane
381		116	W	44.25706. -69.02599							
382			W	44.25685 - 69.02637							Row of Ash/Map;le/Spruce outside of ROW. Stonewall. 8 ft. drainage swale. Ash in group by South Ridge Road entry
383		115	W	44.25670 - 69.02644							South Ridge Road
384			W								Entire span outside ROW
385			E								Entire span outside ROW
386		114	W	44.2563. - 69.2688							
387			W	44.25635 - 69.02724							Several large Maple 2 ft. out of ROW. Long Row of Mature Ash and maple
388		113	W	44.25599 -69.02736							
389			E	44.25607 - 69.02715	D	Black Locust	In v	36	18	Decline	10 ft. RPZ > ROW. Bittersweet Observed. Couple of small ash to the south. 4 ft in ROW
390			E								Stonewall in span
391			W	44.25600 - 69.02743	D	Oak	Inv.	28	14	Good	4 ft. RPZ > ROW. 5 Oaks
392			E	44.25592 - 69.02728	D	Oak	Inv.	24	12	Decline	7 ft. RPZ > ROW. Cluster of four Black Walnut

	A	B	C	D	E	F	G	H	I	J	K
1	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
393			E	44.25571 - 69.02773	D	Red Oak	Group	30	15	Good	
394			E	44.25560 - 69.02760	I	Red Oak	Inv	30	15	Good	9 ft. RPZ > ROW. Large Arborvitae adjacent
395		112	W	44.25560 -69.02779							
396			W	44.25555 - 69.02792	D	Lilac	Inv			Good	At 2076 Atlantic Hwy. Lilac just outside ROW
397			E	44.25538 - 69.02782	E	Arborvitae	Group	10	5	Good	RPZ = ROW. Clutch of 3.
398			E	44.25523 - 69.02801	D	Red Oak	1	60	30	Good	Entire tree is within ROW. 8 feet to white line. RPZ is under Rt. 1
399			E	- 69.02805 - 69.02805	D	Red Oak	I	8	4	Good	2 ft. RPZ > ROW
400			W	44.25522 - 69.02826		Well					Waterwell 14 ft. from white line
401		111	W	44.25519 - 69.02824							
402			W	Red Barn Market Place	E	Arborvitae				Good	30 Arborvitae/Flower Bed and stonewall. 2 ft. out of ROW
403			E	44.25505 - 69.02820	D	Black Walnut?	Group	18	9	Good	7 ft. RPZ > ROW. Clutch of Black Walnut (Not sure)
404			E	44.25499 - 69.02823	D	Ash	Inv	8	4	Good	4 ft. RPZ > RPZ
405			E	44.25499 - 69,02829	D	Horse Chestnut	Inv	54	27	Goode	4 ft. RPZ > ROW. RPZ extends 17 feet un der Road
406			E	44.25482 - 69.02839	D	Ash	Group	10	5	Good	Ash next to Crabapple
407			E	44.25500 - 69.02842	D	Apple	Group	10	5	Good	Group of Apple at Deer Meadows. Well 10 feet out of ROW
408		109	W	44.25437 - 69.02912							
409			E								Service Pole for Deer Meadows

	A	B	C	D	E	F	G	H	I	J	K
1	Seq. #	CMP #	Rt.1 E/W	GPS	D/E	Species	Inv/Group	DBH (Inches)	RPZ Radius (Feet)	Health	Notes (Including Site Issues)
410		109.5	W	44.25459 - 69.02894							
411			E	44.25430 - 69.02805	D	Oak	Inv	48	24	Dead	2 ft. wityhin ROW. MDOT has been informed. Needs Removal.
412			E	44.25407 - 69.02924	E	Spruce	Inv	16	8	Good	5 ft. RPZ > ROW
413		108	W	44.25408 - 69.02946							
414			E	44.25370 - 69.02959	E	White Pine	Inv	36	18	Good	9 ft. RPZ > ROW
415		107	W	44.25377 - 69.02986							
416		106	W	44.25337 - 69.03016							
417			E	44.25322 - 69.02008	E	White Pine	Inv	30	15	Good	7 ft. RPZ > ROW
418		106.5	W	44.25319 - 69.03031							
419		105.5	W	44.25297 - 69.03036							
420		105	W	44.25288 -69.03056							Virginia Drive, Major Culvert between Poles 105-104 crossing road. Large White Pine near culvert.
421			W	44.25277 - 69.03073	E	White Pine	Inv	33	16.5	Good	
422		104	W	44.25255 - 69.03083							Several arborvitae at the ROW
423		103	W	44.25208 - 69.03116							Culvert between Poles 103 and 102. 10 Black Locust outside ROW
424		102.5	W	44.25166. -69.03159							
425			E	44.25156 - 69.03137	E	Arborvitae	Inv	16	8	Good	Culvert egress. Large Oak and many Ash in area.
426		102	W	44.25144 - 69.03182							County/Town Line